

Rolling Bearing Failures and Their Causes

KOYO SEIKO CO., LTD.

1 Improper Fit



■Phenomenon:Fretting Corrosion (Left)/Creep (Right) on Inner Ring Bore Surface Cause:Less Interference Fit with Shaft

■Phenomenon:Scuffing on Inner Ring Bore Surface

Cause:Excessive Interference Fit with Shaft

7 Mishandling

6 Improper Lubrication



and Inner Ring Rib Cause:Improper Lubrication Method or Inappropriate Lubricant



Improper Adjustment



Phenomenon:Smearing on Raceway Cause:Improper Preload



Phenomenon:Seizure at Roller End Surface and Inner Ring Rib

Cause:Insufficient Bench End Play



■ Phenomenon: Dents on Retainer Cause:Retainer Received Impact



■Phenomenon:Scratches (Left)/Scuffing (Right)



Phenomenon:Flaking at Intervals on Roller Pitch (Due to Scratches and Scuffing) Cause: Careless Handling during Assembling



■Phenomenon:Scuffing on Bore Surface Cause:Diagonal Assembly or Foreign Matter

3 Misalignment (Inclination of Bearings)



Phenomenon:Symmetrical Fretting on Upper and Lower Sides Cause:Misalignment



Phenomenon:Retainer Broken
Cause:Abnormal Load due to Misalignment



■Phenomenon:Flaking on Opposite Faces of Raceway

Cause:Diagonal Assembly

B Corrosion



■Phenomenon:Rust Generated on Raceway at Intervals on Roller Pitch Cause:Bearings Left Unused for Long Period under Moist Conditions



Phenomenon:Rust Generated on One Row of Raceway

Cause:Water Contamination during Operation

9 Electric Pitting



Phenomenon:Retainer Broken
Cause:Excessive Vibration or Impact during Operation



Cause:Indentations Caused by Impact Load



Phenomenon:Cracks and Chips on Inner and Outer Rings and Rollers (Left)/
Seizure Caused by Chips on Ribs (Right)

Cause:Excessive Axial Impact Load





Phenomenon:Flaking Generated Around Half the Raceway Cause:Flaking Caused by Rust



5 Dirty Lubricant

4 Impact Load



Phenomenon:Indentations on Raceway





Phenomenon:Smearing/Wear on Roller
Cause:Lubricant Contaminated by Water or Other Foreign Matter



KOYO SEIKO CO., LTD. (Japan) is certified to ISO9001 and QS-9000.





■Phenomenon:Electric Pitting (Pit-or Ridge-) and Staining Cause: Current Passed Through Inside of Bearing